

COMMISSIONER'S MONTHLY REPORT

Commissioner

BOARDMAN SPRING, THOMAS SPRING AND VICINITY

Date Aug 20, 1965 1965  
Report for Month of August 1965

Source and Point of Measurement	Day of the Month														
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30
I. Boardman Springs															
#1. Pacific States Cast Iron Pipe Co. (down stream from Pipe Line)															
#2. Boardman Springs Channel by U. S. Highway #91 (This reading does not include #1 or Pacific States Cast Iron Pipe Co. Water)			2.27 sec ft		3.18 sec ft										
#3. Church ditch near to heading			0.32		0.32										
#4. Boardman Spring water before it joins Thomas Spring (This has a pick up of miscellaneous small springs along the RR right-of-way)			0.02		0.02										
#7. Boardman Spring Waste Channel to #9 (pump) and to Utah Lake			1.30		1.50										
II. Thomas Spring															
#5. Above the Olsen house below the tracks			0.30		0.30										
III. Drain															
#6. Drain Channel near Railroad Shop and Burningham properties			2.66		3.01										
IV. #8. Levie Ditch - Water to Church Farm, etc.			1.0		1.0										
V. #9. Pump Water at Church Welfare Farm			None		*3.16										

For key to location numbers see drawing P-5107

\* 1341 of Thomas & North Springs by passing to lake - Church Farm using this water  
P.S.C.E.P. Co. Using all of Boardman Springs on North Reading's  
Submitted by E. Lewis Allen